



Junker Ju 88 In Finnish service

Junker Ju 88 in Finnish service (Source : Suomen Ilmavoimien Historia 9 , Keskinen et. al)

Type	WerkNr.088	German registration	German units	Finnish Registration	History	Finnish units
A-4/R	3880	GB+YJ		JK-251	Delivered 10/4 1943, crashed 29/12 1943	LeLv. 44
A-4/R	3878	GB+YH		JK-252	Delivered 10/4 1943, used as a crew trainer after the war	LeLv. 44, PLeLv. 44, PLeLv. 43
A-4/R	3879	GB+YL		JK-253	Delivered 10/4 1943, landing damage 26/8 1947 and not repaired	LeLv. 44, PLeLv. 44, PLeLv. 43
A-4/R	3883	DJ+TC		JK-254	Delivered 10/4 1943, crashed 1/7 1944	LeLv. 44
A-4/R	3889	DJ+TI		JK-255	Delivered 10/4 1943, landing damage 1/6 1944 and not repaired	LeLv. 44
A-4/R	3860	GL+QM		JK-256	Delivered 20/4 1943, shot down by german fighter 10/10 1944	LeLv. 44
A-4/R	3887	DJ+TG		JK-257	Delivered 20/4 1943, used as a trainer after the war	LeLv. 44, PLeLv. 43
A-4/R	8797	CT+ZA		JK-258	Delivered 20/4 1943, used as a trainer after the war	LeLv. 44, PLeLv. 43
A-4/R	3845	BI+EY		JK-259	Delivered 20/4 1943, shot down 23/6 1944	LeLv. 44
A-4/R	8785	CP+OO		JK-260	Delivered 20/4 1943, crashed 5/6 1946	LeLv. 44, PLeLv. 44
A-4/R	3857			JK-261	Delivered 20/4 1943, crashed 5/6 1946	LeLv. 44, PLeLv. 43
A-4/R	3899	DJ+TS		JK-262	Delivered 11/4 1943, exploded during landing 18/7 1944	LeLv. 44
A-4/R	3863	KG+KE		JK-263	Delivered 11/4 1943, shot down by german AA 15/10 1944	LeLv. 44, PLeLv. 44
A-4/R	8794	CP+OX		JK-264	Delivered 20/4 1943, crashed 15/6 1944	LeLv. 44, PLeLv. 44
A-4/R	3877	GE+YG		JK-265	Delivered 10/4 1943, put into storage 17/10 1945	LeLv. 44, PLeLv. 43
A-4/R	3885	DJ+TE		JK-266	Delivered 1/4 1943	LeLv. 44, PLeLv. 43
A-4/R	3888	DJ+TH		JK-267	Delivered 11/4 1943, damaged during take-off 29/7 1944 and was not repaired	LeLv. 44
A-4/R	8796	CP+OZ		JK-268	Delivered 20/4 1943, used as a trainer after the war	LeLv. 44, PLeLv. 44, PLeLv. 43
A-4/R	3882	DJ+TB		JK-269	Delivered 10/4 1943, damaged by own bombs 20/8 1943 was repaired and stored	LeLv. 44
A-4/R	3881	DJ+TA		JK-270	Delivered 10/4 1943, crashed 18/6 1947	LeLv. 44, PLeLv. 43
Ju 88 at Tutow before going to Finland				Ju 88 inspected by the Finnish crew	JK-251	LeLv. 44, PLeLv. 44, PLeLv. 43
						LeLv. 44, PLeLv. 44, PLeLv. 43
						LeLv. 44, PLeLv. 44, PLeLv. 43
						LeLv. 44, PLeLv. 43
				land 23/4		LeLv. 44